.01 OHM SHUNT (INSTALLED WITH ANODE ONLY)

6"

1.5"   3"

CONNECT 1-#6 TEST LEAD FROM ANODES. IF THERE ARE NO ANODES, THIS CONNECTION POINT SHALL BE A SPARE.

CONNECT 1-#6 HMWPE TEST LEAD FROM PIPE

ANODE LEAD

SHUNT .01 OHMS

PIPE LEAD #1

CONNECT 1-#6 HMWPE TEST LEAD FROM A 200' DISTANCE

CONNECT 1-#6 HMWPE TEST LEAD FROM PIPE

SPAN LEAD #1

PIPE LEAD #2

2"

CONNECT 1-#6 HMWPE TEST LEAD FROM A 200' DISTANCE

CONNECT 1-#14 HMWPE REFERENCE CELL TEST LEAD

SPAN LEAD #2

REF. LEAD

2"

10"

CONNECT 1-#6 HMWPE TEST LEAD FROM A FOREIGN PIPE (SEE NOTE)

CONNECT 1-#6 HMWPE TEST LEAD FROM A FOREIGN PIPE (SEE NOTE)

FOREIGN LEAD #2

FOREIGN LEAD #1

2"

2"

LABEL 1/2" HIGH BLOCK LETTERS (BLACK ON WHITE, TYPICAL)

MICARTA BOARD

FOR TEST LEAD LUG CONNECTIONS, SEE (X / XXXX) (PL12-3C)

NOTE:
IF NO FOREIGN PIPES ARE IDENTIFIED TO BE CONNECTED, CHANGE "FOREIGN LEAD" LABEL TO "SPARE"

TEST BOARD FOR JOINT TEST STATION

NOT TO SCALE   PL12-3B   020719