



NOTES:

1. CLEARANCE FROM A COLLAR OR PIPE JOINT SHALL BE A MINIMUM OF 2 FEET FROM THE EDGE OF TAPPING SLEEVE TO COLLAR OR PIPE JOINT. THE EXISTING PIPE SHALL BE EXPOSED SUFFICIENTLY TO ENSURE THAT SUCH MINIMUM CLEARANCE IS PROVIDED.
2. TRENCH SHALL MEET ALL OSHA REQUIREMENTS.
3. GATE VALVE TO BE TEMPORARILY SUPPORTED DURING THE WET TAP PROCESS.

EXCAVATION FOR WET TAPS

NOT TO SCALE

PL15-3 070703

